

Message

---

**From:** Andrae, Bill/MKE [William.Andrae@jacobs.com]  
**Sent:** 9/17/2020 9:09:54 PM  
**To:** Giancarlo, Mary Beth [Giancarlo.Marybeth@epa.gov]  
**CC:** Skwarski, Alison/DET [Alison.Skwarski@jacobs.com]; Reif, Marty/WDC [Marty.Reif@jacobs.com]; Klinkhamer, Christopher [Klinkhamer.Christopher@epa.gov]  
**Subject:** Gorge Dam Sediment Sampling Field Effort  
**Attachments:** WinchSystem\_091520.jpg; FloatingDock\_091520.jpg; DockArea\_PreSampling\_091520.jpg

Mary Beth – Jacobs' staff (Alison Skwarski and JTannar Wiens) successfully completed the sediment sampling yesterday. On Tuesday (9/15) they collected 13 of the 18 buckets and collected the last 5 on Wednesday morning. The sediment collection went very well with no mechanical or health & safety issues. Diedre May/SMP met our field team and verified the team could drive down to the floating dock. A few pictures are attached for your viewing pleasure.

Staff from Tipping Point arrived on Wednesday morning and took possession of the sediment and then Jacobs and Tipping Point staff conducted a tour of the Chuckery Area and walked the Highbridge Trail.

The sediment was successfully delivered to the treatability laboratory and sample preparation will begin this week.

Please let me know if you have any questions.

Cheers!

Bill

**Bill Andrae** | Jacobs | Design Manager / Environmental Engineer  
O: +01.414.847.0341 | M: +01.262.366.0968 | [william.andrae@jacobs.com](mailto:william.andrae@jacobs.com)  
1610 North 2<sup>nd</sup> Street Suite 201 | Milwaukee, WI 53212 | USA

**Jacobs** Challenging today.  
Reinventing tomorrow.

---

NOTICE - This communication may contain confidential and privileged information that is for the sole use of the intended recipient. Any viewing, copying or distribution of, or reliance on this message by unintended recipients is strictly prohibited. If you have received this message in error, please notify us immediately by replying to the message and deleting it from your computer.